














































PENTAX K-5

PENTAX K-3 III

 1	USER Mode	USER	 1	Recall User Mode Setting			
	Exposure Mode	USER		 5	Exposure in User Mode		
	File Format				File Format		
	JPEG Recorded Pixels				JPEG Recorded Pixels		
	JPEG Quality				JPEG Quality		
	AUTO AF Point Setting				 1	AF with Viewfinder	AF Active Area
Lens Correction	Distortion Correction Lat-Chromatic-Ab Adj	 6	Lens Correction	Distortion Correction Lat-Chromatic-Ab Adj			
 2	Cross Processing			 6	Custom Image		
	Extended Bracketing						
	Digital Filter		 6		Digital Filter		
	HDR Capture				 4	HDR Capture	
	Multi-exposure					Drive Mode	[Drive ↳[Multi-exposure]
	Interval Shooting					Drive Mode	[Drive ↳[Interval Shooting]
	Composition Adjust.	Composition Adjust.					 7
Recall Previous Position				 5		Memory	
 3	D-Range Setting	Highlight Correction	 6		D-Range Correction	Highlight Correction Shadow Correction	
		Shadow Correction					
	ISO AUTO Setting		 2	ISO Sensitivity Setting			
	High-ISO NR			 6	Noise Reduction	Slow Shutter Speed NR High-ISO Noise Reduction	
	Slow Shutter Speed NR						
	Program Line		 2	Program Line			
	Color Space		 5	Color Space			
	RAW File Format		 5	RAW File Format			
 4	Movie	Recorded Pixels	 5	Recorded Pixels			
		Quality Level		 5	Framerate		
		Sound			Recording Sound Level		
		Cross Processing			Custom Image		
		Digital Filter			Digital Filter		
		Movie Aperture Control			Live View		
		Shake Reduction			 7	Shake Reduction	
Live View	Autofocus Method		 1	AF with Live View	AF Active Area Face Detection		
	Show Grid			 4	Monitor Display	[Live View ↳[Shooting Info Display] ↳[L1 Customization] ↳[L2 Customization] ↳[L3 Customization]	
	Info Overlay		Live View		INFO		
	Histogram		 4		Monitor Display	[Live View ↳[Shooting Info Display] ↳[L1 Customization] ↳[L2 Customization] ↳[L3 Customization]	

PENTAX K-5

PENTAX K-3 III

 4	Live View	Bright/Dark Area	 4	Monitor Display	[Live View] ↳[Shooting Info Display] ↳[L1 Customization] [L2 Customization] [L3 Customization]		
	Electronic Level			 4	Viewfinder Display	[Viewfinder Screen] ↳[F1 Customization] [F2 Customization] [F3 Customization] [F4 Customization] Electronic Level Type	
	Horizon Correction		 4		Monitor Display	[Live View] ↳[Shooting Info Display] ↳[L1 Customization] [L2 Customization] [L3 Customization] [Live View] ↳[Electronic Level Type] [Live View] ↳[Electronic Level Design]	
	Shake Reduction			 7	Auto Horizon Correction		
	Input Focal Length			 7	Shake Reduction		
 5	Instant Review	Display Time	 6	MF Lens Focal Length			
		Histogram		 4	Instant Review	Display Time	
		Bright/Dark Area				Histogram	
		Enlarge Instant Review				Highlight Alert	
	Digital Preview		Zoom Review				
	E-Dial Programming		 2	Preview Dial	Digital Preview Settings		
	Button Customization	RAW/Fx Button	 2	E-Dial Programming			
		AF Button	 2	Fx Button			
		Preview Dial	 2	AF/AE Lock Settings			
		Shutter Button Half Press	 2	Preview Dial			
Memory		 2	AF/AE Lock Settings				
Save USER Mode	Save Settings	 5	Memory				
	Rename USER Mode	 1	Save User Mode Settings				
	Check Saved Settings	 1	Rename User Mode				
	Reset USER Mode		 1	Reset User Mode Settings			

PENTAX K-5



















PENTAX K-3 III

▶ 1	Slideshow	
	Quick Zoom	
	Bright/Dark Area	
	Auto Image Rotation	
	Delete All Images	
↷ 1	Language/言語	
	Date Adjustment	
	World Time	
	Text Size	
	Beep	
	Guide Display	
	Status Screen	Status Screen
		Auto Screen Rotation
		Display Color
	↷ 2	Brightness Level
LCD Color Tuning		
Video Out		
HDMI Out		
USB Connection		
Folder Name		
Create New Folder		
↷ 3	File Name	
	Copyright Information	Embed Copyright Data
		Photographer
		Copyright Holder
	Auto Power Off	
Select Battery	Select Battery	
	AA Battery Type	
Reset		
↷ 4	Pixel Mapping	
	Dust Alert	
	Dust Removal	
	Sensor Cleaning	
	Format	

C 4	Zoom Review	Quick Zoom
	C 4	Monitor Display
[Standard Info. Display]		
[No Information Display]		
▶ 1	Auto Image Rotation	
	▶ 2	Delete
↷ 7	Language/言語	
	↷ 7	Date Adjustment
↷ 3	Sound Effects Volume	
	↷ 3	Sound Effects Setting
↷ 2		Guide Display
	Status Screen	Status Screen
C 4		Monitor Display
	[Auto Display Rotation]	
C 4	Monitor Display	Color Settings
		↷ 2
↷ 2	Monitor Adjustment	
↷ 4	USB Setting	
	↷ 1	Folder Name
↷ 1		Create New Folder
	↷ 1	File Name
↷ 1		Copyright Information
	Photographer	
	Copyright Holder	
↷ 5	Auto Power Off	
	↷ 5	Battery Grip Settings
↷ 8	Reset	
	↷ 6	Pixel Mapping
↷ 6	Dust Removal	
	↷ 6	Sensor Cleaning
↷ 1		Format

PENTAX K-5

PENTAX K-3 III

C 1	EV Steps	C 5	EV Steps	
	Sensitivity Steps	C 5	ISO Sensitivity Steps	
	Expanded Sensitivity			
	Meter Operating Time	C 5	Meter Operating Time	
	AE-L with AF Locked	C 2	AF/AE Lock Settings	
	Link AE to AF Point		2 Link AE and AF Point	
Auto EV Compensation		2 Link AE and AF Point		
C 2	Auto Bracketing Order		2 Auto EV Compensation	
	One-Push Bracketing		4 Drive Mode	[Drive └[Bracketing └[Bracketing Order]]
	WB Adjustable Range		4 Drive Mode	[Drive └[Bracketing └[One-Push Bracketing]]
	WB When Using Flash		3 Auto Adjust. for Source	
	AWB in Tungsten Light		3 Auto Adjust. for Source	
	Color Temperature Steps		3 AWB in Tungsten Light	
	Superimpose AF Area		3 AWB in Tungsten Light	
	C 3	AF.S Setting	C 6	Color Temperature Steps
AF.C Setting		C 4		
AF Assist Light			4 Viewfinder Display	[Viewfinder Screen └[F1 Customization [F2 Customization [F3 Customization [F4 Customization]]
AF with Remote Control			1 AF with Viewfinder	Viewfinder Light
Remote Control in Bulb			1 AF Assist Light	AF.S Setting
Release While Charging			1 AF Assist Light	Action in AF.C Cont.
Flash in Wireless Mode		C 6	6 AF with Remote Control	
C 4		LCD Panel Illumination	C 5	5 Bulb (B) Mode Options
		Saving Rotation Info		
		Save Menu Location		
	Catch-in Focus	C 4	4 LCD Panel	Illumination Brightness LCD Panel Illumination
	AF Fine Adjustment	C 6	6 Save Rotation Info	
	Using Aperture Ring		2 Store Cursor Position	
	Reset Custom Functions		1 AF with Viewfinder	Catch-in Focus
		C 7	7 AF Fine Adjustment	
		C 6	6 Using Aperture Ring	
			8 Reset	