

limited 01



























PENTAX K-3 III

📷 1	Phase Detection AF	AF Mode
		AF Active Area
		AF.S Setting
		1st Frame Action in AF.C
		Action in AF.C Cont.
		Hold AF Status
Contrast Detection AF	Contrast Detection AF	Contrast Detection AF
		Focus Peaking
		Contrast AF Options
AF Assist Light		
AE Metering		
ISO AUTO Setting	ISO AUTO Setting	ISO Range (Maximum)
		ISO Range (Minimum)
		AUTO ISO Parameters
Flash Mode		
Program Line		
Exposure Mode USER		
📷 2	LV Electronic Shutter	
Memory Card Options		
Crop		
Image Capture Settings	Image Capture Settings	File Format
		JPEG Recorded Pixels
		JPEG Quality
		RAW File Format
		Color Space
D-Range Settings	D-Range Settings	Highlight Correction
		Shadow Correction
Noise Reduction	Noise Reduction	Slow Shutter Speed NR
		High-ISO NR
📷 3	Clarity	
	Skin Tone	
	Digital Filter	
	HDR Capture	
	Pixel Shift Resolution	
ASTROTRACER	ASTROTRACER	ASTROTRACER
		Precise Calibration
📷 4	AA Filter Simulator	
	Shake Reduction	
	Horizon Correction	
	Composition Adjust.	

📷 1	AF with Viewfinder	AF Mode
		AF Active Area
		AF.S Setting
		1st Frame Action in AF.C
		Action in AF.C Cont.
		Hold AF Status
📷 1	AF with Live View	AF Active Area
		Face Detection
		Focus Peaking
Contrast AF Options		
AF Assist Light		
AE Metering		
📷 2	ISO Sensitivity Setting	ISO Auto Upper Limit
		ISO Auto Lower Limit
		Min. Shutter Speed Op.
		ISO Auto with Min. Speed
		Minimum Shutter Speed
Flash Mode		
Program Line		
Exposure in User Mode		
/		
📷 5	Memory Card Options	Memory Card Options
		Card Slot Sequence
Crop		
File Format		
JPEG Recorded Pixels		
JPEG Quality		
RAW File Format		
Color Space		
📷 6	D-Range Correction	Highlight Correction
		Shadow Correction
📷 6	Noise Reduction	Slow Shutter Speed NR
		High-ISO Noise Reduction
Clarity		
Skin Tone		
Digital Filter		
HDR Capture		
Pixel Shift Resolution		
📷 4	ASTROTRACER	ASTROTRACER
		Precise Calibration
AA Filter Simulator		
Shake Reduction		
Auto Horizon Correction		
Composition Adjustment		

I limited 01

PENTAX K-3 III

 5	Instant Review	Display Time	Instant Review	Display Time	
		Zoom Review		Zoom Review	
		Save RAW Data		Save RAW (RAW Button)	
		Delete		Delete Img. (Delete Btn.)	
		Histogram Display		Histogram	
		Highlight Alert		Highlight Alert	
Other Display Settings	Guide Display	 2 Guide Display			
	Auto Screen Rotation	 4 Monitor Display	[Status Screen]	
	Display Color	 4 Monitor Display	└[Auto Display Rotation		
Button Customization	Fx1 Button	 2 Fx Button			
	Fx2 Button				
	AF Button	 2 AF/AE Lock Settings			
	Preview Dial	 2 Preview Dial			
	E-Dial Programming	 2 E-Dial Programming	Still Image		
Memory			Rotation Direction		
Save USER Mode	Save Settings	 5 Memory			
	Rename USER Mode	 1 Save User Mode Settings			
	Check Saved Settings	 1 Rename User Mode			
	Reset USER Mode	 1 Reset User Mode Settings			
 1	Contrast Detection AF	Contrast Detection AF	 1 AF with Live View	AF Active Area	
		Focus Peaking		Focus Peaking	
	AF Assist Light		 1 AF Assist Light		
	AE Metering		 2 AE Metering		
	Memory Card Options		 5 Memory Card Options		
	Crop				
	Movie Capture Settings	Recorded Pixels	 5 Recorded Pixels		
		Framerate	 5 Framerate		
	Sound Volume Setting	Recording Sound Level	 5 Recording Sound Level		
		Wind Noise Reduction	 5 Wind Noise Reduction		
		Headphone Volume	 5 Headphone Volume		
	D-Range Settings	Highlight Correction	 6 D-Range Correction	Highlight Correction	
		Shadow Correction		Shadow Correction	
	Digital Filter		 6 Digital Filter		
	Movie SR		 7 Shake Reduction		
	Live View	Grid Display	 4 Monitor Display		
			[Live View	[Shooting Info Display]
			└[L1 Customization]	
			[L2 Customization]	
			[L3 Customization]	
			Grid Guide		

2	Live View	Electronic Level	Monitor Display	[Live View]		
		Histogram Display		↳[Shooting Info Display]		
		Highlight Alert		↳[L1 Customization]		
		Flicker Reduction		[L2 Customization]		
Button Customization	AF Button (Movie)		E-Dial Programming	[L3 Customization]		
	E-Dial Programming			[Live View]		
1	Slideshow		AF/AE Lock Settings	[Live View]		
	Protect All Images			E-Dial Programming	↳[Electronic Level Type]	
	Delete All Images				Movie	[Live View]
	Quick Zoom			Protect	↳[Electronic Level Design]	
	Playback Sound Volume				Protect All Images	[Live View]
	Image Display	Auto Image Rotation		Delete	↳[Shooting Info Display]	
		Grid Display			Delete All Images	↳[L1 Customization]
		Highlight Alert		Quick Zoom	[L2 Customization]	
	Language/言語			Zoom Review	Playback Sound Volume	[L3 Customization]
	Date Adjustment			Playback Sound Volume		[Live View]
World Time		Auto Image Rotation	Monitor Display	↳[Playback Info Display]		
Text Size		Grid Display		↳[Standard Info. Display]		
Sound Effects		Highlight Alert		[No Information Display]		
LCD Display Settings		Language/言語	Sound Effects Volume	Grid Guide		
Outdoor View Setting		Date Adjustment		Sound Effects Setting	[Playback Info Display]	
2	Illumination Settings		LCD Panel	↳[Standard Info. Display]		
	Indicator Lamps			Illumination Brightness	↳[No Information Display]	
	Wi-Fi		Wireless LAN Setting			
	GPS/E-Compass	GPS Logging		Indicator Lamps	LCD Panel Illumination	
		GPS Time Sync			Wireless LAN Setting	
		Calibration				Indicator Lamps
	USB Connection		GPS Settings			
	HDMI Out		USB Setting			






I limited 01

PENTAX K-3 III

2	Auto Power Off	5	Auto Power Off
3	Create New Folder	1	Create New Folder
	Folder Name	1	Folder Name
	File Name	1	File Name
	File No.	1	Sequential Numbering
		1	Reset File Number
	Copyright Information	1	Reset Numbering
		1	Copyright Information
			Embed Copyright Data
			Photographer
			Copyright Holder
	Format	1	Format
4	Pixel Mapping	6	Pixel Mapping
	Dust Removal	6	Dust Removal
	Sensor Cleaning	6	Sensor Cleaning
	Select Battery	5	Battery Grip Settings
		6	Certification Marks
		6	Firmware Info/Options
		8	Reset
5	Night Vision LCD Display	2	Night Vision Display
C 1	EV Steps	C 5	EV Steps
	Sensitivity Steps	C 5	ISO Sensitivity Steps
	Meter Operating Time	C 5	Meter Operating Time
	Auto EV Compensation	2	Auto EV Compensation
	Link AE and AF Point	2	Link AE and AF Point
		2	Link AE and AF Point
	Bulb (B) Mode Options	C 5	Bulb (B) Mode Options
	Flash Sync Speed	C 5	X Mode Sync Speed
C 2	AE-L with AF Locked	C 2	AF/AE Lock Settings
	Viewfinder Light	C 4	Viewfinder Display
			Viewfinder Light
	AF with Remote Control	C 6	AF with Remote Control
	Bracketing Order	4	Drive Mode
			[Drive]
			↳ [Bracketing]
			↳ [Bracketing Order]
	One-Push Bracketing	4	Drive Mode
			[Drive]
			↳ [Bracketing]
			↳ [One-Push Bracketing]
	Interval Shooting Options	4	Drive Mode
			[Drive]
			↳ [Interval Shooting]
			[Interval Composite]
			↳ [Fixed Time Release]
	AF in Interval Shooting	4	Drive Mode
			[Drive]
			↳ [Interval Shooting]
			[Interval Composite]
			↳ [AF Operation per Shot]
C 3	WB Adjustable Range	3	Auto Adjust. for Source
		3	Auto Adjust. for Source
	AWB in Tungsten Light	3	AWB in Tungsten Light
		3	AWB in Tungsten Light

Ilimited 01

PENTAX *K-3III*

C 3	WB When Using Flash			
	Color Temperature Steps	C 6	Color Temperature Steps	
	Enable/Disable Control	C 2	Fx Button	
	Change AF Point Button			
	Auto SR Off	 7	Auto Shake Reduction Off	
C 4	Save Rotation Info	 7	Auto Shake Reduction Off	
	Save Menu Location	C 6	Save Rotation Info	
	Catch-in Focus	 2	Store Cursor Position	
	AF Fine Adjustment	 1	AF with Viewfinder	Catch-in Focus
	Using Aperture Ring	C 7	AF Fine Adjustment	
	Reset Custom Functions	C 6	Using Aperture Ring	
			 8	Reset